

ATTACHMENT "A"



SUBJECT: Service Action SD

Dear Suzuki Sidekick Owner:

VIN

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. American Suzuki Motor Corporation has determined that a defect which relates to motor vehicle safety exists in certain 1993-94 Suzuki Sidekick vehicles. According to our records, you own one of the affected vehicles.

Some rear axle housing assemblies in affected vehicles may have been manufactured incorrectly, which could allow a welding fracture at the axle shaft housing tube to the differential case. Fracture of the axle shaft housing could result in loss of rear braking and affect vehicle control, and could cause a vehicle crash without prior warning.

To preclude the possibility of this occurring, your Suzuki dealer will, **at no charge** to you, inspect the rear axle housing assembly and replace the assembly with a new one if it is determined that the assembly was manufactured incorrectly.

Please contact your Suzuki dealer to schedule an appointment for this service. Instructions for the inspection and correction have been sent to your dealer and parts are available for overnight shipment. The inspection can be completed in about 15 minutes. Please ask your dealer if additional time will be needed to process your vehicle. If the rear axle assembly in your vehicle must be replaced, your dealer must order a new rear axle housing assembly and will need to keep your vehicle for one to three days. Alternate transportation, if necessary, will be provided. When you arrive for your pre-scheduled service, please present this letter to your Suzuki dealer. If you no longer own this vehicle, please complete the enclosed postage-paid reply card and return it to us.

If your dealer does not perform the service within a reasonable period of time, we recommend you contact the American Suzuki Customer Relations Department at (800) 934-0934. If you are still not satisfied that American Suzuki and your dealer have done our best to inspect and make the correction if necessary, without charge within a reasonable period of time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 400 Seventh Street, S.W., Washington, DC 20590 or call the toll-free Auto Safety Hotline at (800) 424-9393 (Washington, DC residents may call 366-0123)

We are sorry for any inconvenience this Special Service Campaign may cause, but we are certain you understand our interest in your safety and your continued satisfaction with Suzuki products.

Sincerely,

AMERICAN SUZUKI MOTOR CORPORATION